

Remit to:  
**E. M. Blue's Sons, Inc.**  
 P O Box 9521  
 Houston, TX 77261-9521



1801 Wayside Drive  
 Houston, TX 77011  
 Phone 713-926-6007  
 Fax 713-921-2641

Email: embues@sbcglobal.net Website: embues.com

**SOLD TO:**

TDI-BROOKS INT'L  
 ATTN: ACCOUNTS PAYABLE  
 1902-PINION DRIVE  
 COLLEGE STATION, TX 77845-5816

**SHIP TO:**

TDI-BROOKS INT'L  
 1902 "D" PINION DR  
 COLLEGE STATION, TX 77845

INVOICE# INVCE-DATE SALESPERS  
 210980 JUN 01 2010 HS

REQ-DATE SHIP VIA  
 APR 29 2010 UPS GRCUND

WGHT PGE

CUST# CUST PO NUMBER  
 TDI3RK SHANNON SMITH

CCC-REQ# SUBJ TERMS  
 NET 30

FREIGHT TRMS FOB  
 PREPAY & ADD ORIGIN

INSD SALES  
 GS

OR'D	SHIP	BKOR	PRODUCT	UNIT	DESCRIPTION	UNIT \$	EXTENDED
6	6		MSTEST	EA	CUSTOMER'S USED 5/8" DIA YELLOW PLASMA ROPE, SUBJECTED TO A DESTRUCTIVE TENSILE TEST.	113.00	678.00
					1-BLK TAPE BROKE @ 36,092#		
					2-YELLOW TAPE BROKE @ 33,692#		
					3-BROKE @ 31,767#		
					4-200 FT. BROKE @ 33,996#		
					5- 400 FT. BROKE @ 35,153#		
					6- 800 FT. BROKE @ 35,485#		
			495CC01		FREIGHT		31.15

**PAID**  
 JUL 06 2010

SUB-TOTAL AMOUNT 709.15  
 SALES TAX

TOTAL AMOUNT 709.15

FILE COPY

Wire rope and fitting products will break if abused, misused or overused. Regular inspections and maintenance are necessary. Consult industry recommendations and OSHA standards before using. WARRANTY: Seller expressly excludes all warranties, guarantees and representations, expressed or implied, including but not limited to warranties of merchantability, materials, workmanship, design and suitability for a purpose specified or intended.