






SECTION 11.02 11.4 SS  
LAB INSTALLATION IN ESVAE

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55



DATE	11/12
BY	SS
DESCRIPTION	LABORATORY
REVISIONS	
1	ISSUED FOR CONSTRUCTION
2	REVISED TO SHOW REVISIONS
3	REVISED TO SHOW REVISIONS
4	REVISED TO SHOW REVISIONS
5	REVISED TO SHOW REVISIONS

U.S. NAVY SHIP REPAIRING COMMAND  
 OCEANOGRAPHIC RESEARCH SHIP  
 HULL # 1141  
 OFFICE COPY

21N TO BR 18 EXCEPT AS NOTED  
 ESVAE # 55





21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
ESVAE # 55



21N TO BR 18 EXCEPT AS NOTED  
 ESVAE # 55

21N TO BR 18 EXCEPT AS NOTED  
 ESVAE # 55